Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080048-1

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11634

RECEIVED FROM

DATE REC'D 3-21-57

P.O. NO.

VENDOR PACKING SLIP NO.

| CHARGE TO | CONTRACT CODE NO. | DRAWING NUMBER | DWG. CLASS OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | ACCT. OR W.O. NO. | S.O. NO. |
|---|---|---|---|---|---|---|---|---|---|---|
| | 322 | | 359 | C | 10 | | | | | |

| QUANTITY RECEIVED | DRAWING NO. AND DESCRIPTION | QUANTITY ACCEPTED | QUANTITY REJECTED | REMARKS |
|---|---|---|---|---|
| 50 | 737537 Lever Asbly Flutter Cam Stop | 50 | ✓ | |
| | IP: 304792 | | | |

RECEIVED BY L. Barcelos

INSPECTED BY Qua DATE 3/22/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11668

RECEIVED FROM

Globe Electrical Company

DATE REC'D 3-22-57

P.O. NO.

VENDOR PACKING SLIP NO. 67[illegible]

| CHARGE TO | CONTRACT CODE NO. | DRAWING NUMBER | DWG. CLASS OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | ACCT. OR W.O. NO. | S.O. NO. |
|---|---|---|---|---|---|---|---|---|---|---|
| | 322 | | 73 | [illegible] | 11 | 1 | | | | |

| QUANTITY RECEIVED | DRAWING NO. AND DESCRIPTION | QUANTITY ACCEPTED | QUANTITY REJECTED | REMARKS |
|---|---|---|---|---|
| 8 | 730[illegible]-GRL Relay - DPDT 15 Amp Globe [illegible] Hermetic sealed | 8 ✓ | | |

RECEIVED BY L. Barcelos

INSPECTED BY

DATE 3-22-57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1069

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080048-1